



**R3 Inspections, LLC**  
**P.O. Box 152205**  
**Cape Coral, FL 33915**  
**Office: 239.810.7793**  
**Email: radjrsas@yahoo.com**



**FRONT ELEVATION VIEW**



**SIDE ELEVATION VIEW**



**REAR ELEVATION VIEW**



**SIDE ELEVATION VIEW**

**Terrace IV at Heritage Cove Association**  
**14091 Brant Point Circle, Fort Myers, FL 33919**  
**01-12-2012**



R3 Inspections, LLC  
P.O. Box 152205  
Cape Coral, FL 33915  
Office: 239.810.7793  
Email: radjrsas@yahoo.com



ROOF DECK THICKNESS



ROOF DECK ATTACHMENT



ROOF DECK ATTACHMENT



REINFORCED MASONRY IF APPLICABLE

Terrace IV at Heritage Cove Association  
14091 Brant Point Circle, Fort Myers, FL 33919  
01-12-2012






R3 Inspections, LLC  
P.O. Box 152205  
Cape Coral, FL 33915  
Office: 239.810.7793  
Email: radjrsas@yahoo.com



ROOF TO WALL ATTACHMENT



ROOF TO WALL ATTACHMENT



GABLE END BRACING IF APPLICABLE



SECONDARY WATER BARRIER – Is not present.

Terrace IV at Heritage Cove Association  
14091 Brant Point Circle, Fort Myers, FL 33919  
01-12-2012





**R3 Inspections, LLC**  
**P.O. Box 152205**  
**Cape Coral, FL 33915**  
**Office: 239.810.7793**  
**Email: radjrsas@yahoo.com**



**OPENING PROTECTION – Some of the glazed openings lack wind-borne debris protection.**

**OPENING PROTECTION**



**OPENING PROTECTION**

**OPENING PROTECTION**